








VEHICLE		TYPE	CLUTCH KIT	COVER ASSEMBLY	DRIVEN PLATE	RELEASE BEARING
						
		ins/mm				

## NISSAN-DATSUN

### Bluebird

160B, 180B (610,810,J910) engs.L16 L18S	73-83	200	HK8197●	HE1222	HB8169●	HD1062
200B (J910) engs.L18S, L18T	79-10/83	200	HK8197●	HE1222	HB8169●	HD1062
200B diesel	79-10/83	200	HK9444●	HE1222	HB8169●	HD5723

1800, 2000 L,LX (U11) engs.CA18S,CA20S	10/83-6/86	200	HK8202●	HE1222	HB8184●	HD3875
1600 L,LX (T12,T72) eng.CA16S	7/86-8/88	215	HK8597●	HE5316	HB8474●	HD5340
1600 L,LX (T72) eng.CA16S	8/88→	215	HK8597●	HE5316	HB8474●	HD5340
1800 (T72) eng.CA18	7/86→	215	HK9153●	HE5316	HB8475●	HD5540
1800 ZX Turbo (U11) eng.CA18ET	5/84-3/86	225	HK9297●	HE5272	HB8330●	HD5539
1800 Turbo (T12, T72) eng.CA18ET	7/86-8/88	225	HK9298●	HE5272	HB8510●	HD5539
1800 ZX Turbo (T72) eng.CA18ET	8/88→	215	HK9153●	HE5316	HB8475●	HD5540
2000 (U11)	11/83-1/86	200	HK8202●	HE1222	HB8184●	HD3875
2000 DX (U11) Estate eng.CA20S	3/86-5/88	215	HK9153●	HE5316	HB8475●	HD5540
2000 (T12,T72) eng.CA20	7/86-8/88	215	HK9153●	HE5316	HB8475●	HD5540
2000 (T72) eng.CA20	8/88→	225	--	--	--	HD5539
2000 diesel (U11) eng.LD20	5/84-1/86	200	HK9154●	HE1222	HB8506●	HD5539
2000 diesel (T12,T72) eng.LD20	2/86→	200	HK9154●	HE1222	HB8506●	HD5539
2000 Turbo diesel (U11) eng.LD20T	11/83→	225	HK9155●	HE5273	HB8510●	HD5539

### Cedric, Gloria

2800 (P430) eng.L28	6/79-83	225	HK8600●	HE5273	HB8352●	HD1062
2800 diesel (H430) eng.LD20	10/79→	240	HK8601●	HE5285	HB8482●	HD1062

### Cherry (inc.Van)

100A (E10) eng.A10	70-73	160	HK8594●	HE1224	HB8162●	HD1250
100A (E10) eng.A10	74-77	160	HK8192●	HE1224	HB8162●	HD2382
120A (E10) eng.A12	70-75	190	HK8195●	HE1223	HB8168●	HD2382
1000 F11 (F10) eng.A10	75-79	160	HK8192●	HE1224	HB8162●	HD2382
1000 (N10) eng.A10	5/78-7/81	160	HK8192●	HE1224	HB8162●	HD2382
1000 (N10) eng.E10	8/81-6/82	160	HK8661●	HE5011	HB8660●	HD5339
1000 (N12) eng.E10	4/82-86	160	HK8661●	HE5011	HB8660●	HD5339

1200 F11 (F10) eng.A12	75-79	190	HK8195●	HE1223	HB8168●	HD2382
1200 (N10) eng.A12	5/78-7/81	190	HK8195●	HE1223	HB8168●	HD2382
1300 (N10) eng.E13	81-82	180	HK8365●	HE1090	HB8363●	HD3875
1300 (N12) eng.E13	4/82-6/86	180	HK8365●	HE1090	HB8363●	HD3875
1400 (N10) eng.A14	5/78-7/81	190	HK8195●	HE1223	HB8168●	HD2382
1500 (N10,N12) eng.E15E	81-86	180	HK8367●	HE1220	HB8363●	HD3875
1500 Turbo (N12) eng.E15ET	5/83-86	200	HK9237●	HE5630	HB8184●	HD3875
1600 (N12)	6/85-5/86	180	HK8367●	HE1220	HB8363●	HD3875
1700 diesel (N12) eng.CD17	5/83-86	180	HK9156●	HE1090	HB8177●	HD5543

### Cherry Europe

1200 (920A)	83-85	180	HK2799 HK8260●	HE1187	HB1867 HB8242●	HD2341
1500 (920A)	83-85	200	HK4820 HK8270●	HE2339	HB2340 HB8247●	HD2341