







		CLUTCH KIT	COVER ASSEMBLY	DRIVEN PLATE	RELEASE BEARING
		 ins/mm			

OPEL - continued

1.4, 1.4i	89→	190	HK9075●	HE5127	HB8445●	HD5005
1.5 Turbo diesel (eng. 15DTR/TC4EC1)	88→	200	--	--	HB8446●	HD3682
1.6S	9/84-8/86	203	HK3970 HK8904●	HE3723	HB3879 HB8824●	HD3880
1.6S, 1.6i (cat converter)	9/86→	200	HK9076●	HE5033	HB8448●	HD5005
1.6 diesel (F16 gearbox)	9/84→	215	HK5051	HE4553	HB4556	HD3880
→eng. 14310804		203	HK8935●		HB8833●	
eng. 14310805 - 14478630 (F16 g/box)		203	HK9077●	HE3723	HB8446●	HD3880
eng. 14478631→ (F16 gearbox)		200	HK9078●	HE5128	HB8446●	HD5130
1.6 diesel (F13 gearbox)	86→	200	HK9079●	HE5033	HB8447●	HD5005
1.7 diesel (F16 gearbox)	88→	200	HK9078●	HE5128	HB8446●	HD5130
1.8N Export (F16 gearbox)		200	HK9078●	HE5128	HB8446●	HD5130
1.8N Export (F13 gearbox)		203	HK9090●	HE5128	HB8446●	HD5005
1.8i, 1.8GSi →eng. 14348330	9/84→	215	HK9182●	HE4553	HB8450●	HD3880
eng. 14348331→ (F16 gearbox)			HK9080●	HE5129	HB8450●	HD5130
2.0GSi (F13 gearbox)	9/86→	215	HK9088●	HE5129	HB8451●	HD5005
2.0GSi (F16 gearbox)	9/86→	215	HK9087●	HE5129	HB8451●	HD5130
2.0GSi 16v	3/88→	228	HK9081●	HE5315	HB8452●	HD5130
Kapitain/Admiral						
2.6, 2.8	64-77	228	HK2787 HK8874●	HE3630	HB2200 HB8782●	HD3682
Monza/Senator						
2.0, 2.2i	82→	228	--	HE3630	--	HD3682
2.5, 2.8 4 speed	78→	228	--	--	HB2200 HB8782●	HD3682
Olympia						
1.1	67-70	170	HK2365 HK8858●	HE1047	HB1048 HB8723●	HD3270
1.5, 1.7, 1.9	67-70	203	HK4560 HK8075●	HE1049	HB3850 HB8065●	HD3682
Omega						
1.8S, 1.8SE	9/86→	203	HK9082●	HE5128	HB8455●	HD5005
1.8 eng. 18SVE, 18NVR →ch. J1162494	9/86→					
1.8 eng. 18NV →ch. J1153529	9/86→					
1.8i eng. 18SEM	9/86→	215	HK9084●	HE5129	HB8454●	HD5005
1.8 eng. 18SVE, 18NVR ch. J1162495→						
1.8 eng. 18NV →ch. J1153530→						
2.0i, 2.0i (cat converter)	9/86→	215	HK9084●	HE5129	HB8454●	HD5005
2.3 diesel, Turbo diesel	9/86→	228	HK9113●	HE5499	HB8699●	HD5005
Rekord B/C						
1.5, 1.7, 1.9, 2.2 ▲ ¹	65-71	203	HK4560 HK8075●	HE1049	HB3850 HB8065●	HD3682

NOTE: ▲¹Technical note see page 54.