









				CLUTCH KIT	COVER ASSEMBLY	DRIVEN PLATE	RELEASE BEARING
			 ins/mm				

BMW - continued

7 Series

728 (E23), 730 (E23)	77-79	240	HK4989 HK8919●	HE1214	HB1022 HB8718●	HD1225
728i (E23)	79-84	240	HK4989 HK8919●	HE1214	HB1022 HB8718●	HD1225
732i (E23), 733i (E23)	77-8/83	240	--	HE2410	--	HD1225
735i (E23)	79-8/83	240	--	HE2410	--	HD1225
1502	75-77	200	HK3563 HK8883●	HA1018	HB1020 HB8716●	HD1234
1600-1, 1600-2	64-71	200	HK3563 HK8883●	HA1018	HB1020 HB8716●	HD1234
1602	64-71	200	HK3563 HK8883●	HA1018	HB1020 HB8716●	HD1234
Touring 1600, 1602	71-76	200	HK3563 HK8883●	HA1018	HB1020 HB8716●	HD1234
1600 Ti, GT	67-68	200	--	--	HB1020 HB8716●	HD1234
1800 Ti	64-71	200	--	--	HB1020 HB8716●	HD1234
1800 Ti SA	65-71	228	--	--	HB1021 HB8717●	HD1010
1800, 1802, Touring	71-8/73	228	HK2774 HK8869●	HE1213	HB1021 HB8717●	HD1011
1802, Touring	9/73-76	215	HK2775 HK8870●	HE1246	HB1967 HB8062●	HD1234
2002 →ch. 1626693	65-71	228	HK5551 HK9167●	HA1020	HB1021 HB8717●	HD1010
2002 RL →ch. 1651034	65-71	228	HK5551 HK9167●	HA1020	HB1021 HB8717●	HD1010
2002 US →ch. 1665243	65-71	228	HK5551 HK9167●	HA1020	HB1021 HB8717●	HD1010
2002 TI →ch. 1681795	65-71	228	HK5551 HK9167●	HA1020	HB1021 HB8717●	HD1010
2002 ch. 1626694→	71-73	228	HK2774 HK8869●	HE1213	HB1021 HB8717●	HD1011
2002 RL ch. 1651035→	71-73	228	HK2774 HK8869●	HE1213	HB1021 HB8717●	HD1011
2002 US ch. 1665244→	71-73	228	HK2774 HK8869●	HE1213	HB1021 HB8717●	HD1011
2002 TI ch. 1681796→	71-73	228	HK2774 HK8869●	HE1213	HB1021 HB8717●	HD1011
2002, Touring 2002,	9/73-75	215	HK2775 HK8870●	HE1246	HB1967 HB8062●	HD1234
2002 RL, 2002 US	9/73-75	215	HK2775 HK8870●	HE1246	HB1967 HB8062●	HD1234
2002 Tii, Touring 2002 Tii	71-75	228	HK2774 HK8869●	HE1213	HB1021 HB8717●	HD1011
2500	→9/73	240	HK5146 HK8943●	HE1214	HB1022 HB8718●	HD1234
2500, 2.5 CS	10/73-77	240	HK4989 HK8919●	HE1214	HB1022 HB8718●	HD1225