








CLUTCH RELEASE BEARING	DRIVEN PLATE	COVER ASSEMBLY	CLUTCH KIT	CLUTCH PRESSURE PLATE	COVER ASSEMBLY	DRIVEN PLATE	RELEASE BEARING
							
		ins/mm					

VOLKSWAGEN - continued

2.0 (JS/HP/SK/eng.)→ch 32H4000000	83→	215	HK8705●	HE1246	HB8700●	HD1020	
2.0 (JS, HP, SK eng.) ch. 32J000001	→3/88	228	HK8385●	HE2207	HB8360●	HD1020	
2.0 Syncro (HP/JS/SK eng.)	84-3/88	228	HK8385●	HE2207	HB8360●	HD1020	
2.0 16v (GA eng.)	8/88→	228	HK9493●	HE5735	HB9491●	HD5693	
2.2 (WB eng.)	9/82-7/83	215	HK8705●	HE1246	HB8700●	HD1020	
2.2 GT (HY/KV/KX eng.)	85-3/88	228	HK8385●	HE2207	HB8360●	HD1020	
2.2 Syncro (HY eng.)	84-3/88	228	HK9473●	HE2207	HB9468●	HD1020	
2.2 Syncro (JT eng.)	85-3/88	228	HK8385●	HE2207	HB8360●	HD1020	
Polo/Derby							
0.8 (HE eng.)	76-77	180	HK2447	HE1240	HB1960	HD1232	
0.9 (HA eng.)	75-81		HK8071●		HB8061●		
1.0 (AAU eng.)	10/90→	190	HK9114●	HE5500	HB8702●	HD5002	
1.05 (GL eng.) →ch. G-050 000	81→	180	HK2447	HE1240	HB1960	HD1232	
1.05 (GL eng.) ch. G-050 001→	→5/86	180	HK8071●		HB8061●		
1.05 (GL eng.) ch. G-050 001→			HK5003	HE1240	HB1960	HD5002	
1.05 (GL eng.) ch. G170 001→	→10/86	190	HK8921●		HB8061●		
1.05 (HZ eng.) →ch. G-050 000	8/85→	180	HK9114●	HE5500	HB8702●	HD5002	
1.05 (HZ eng.) ch. G-050 001 to G-170 000		180	HK2447	HE1240	HB1960	HD1232	
1.05 (HZ eng.) ch. G170 001→	→10/86	190	HK8071●		HB8061●		
1.1 (HB, HC, HD eng.)	74-83	180	HK5003	HE1240	HB1960	HD5002	
			HK8921●		HB8061●		
			HK9114●	HE5500	HB8702●	HD5002	
			HK2447	HE1240	HB1960	HD1232	
			HK8071●		HB8061●		
1.3 (GT eng.) →eng. 009 203	8/82→	180	HK2447	HE1240	HB1960	HD1232	
1.3 (GT eng.) eng. 009 204 to 016 142	→7/85	190	HK8071●		HB8061●		
1.3 (GT eng.) eng. 016 143→	→10/86	190	HK9186●	HE5525	HB8292●	HD1232	
1.3 (GK eng.) →ch. G-015 000	9/82→	190	HK9114●	HE5500	HB8702●	HD5002	
1.3 (GK eng.) ch G015 001→	→10/86	190	HK9186●	HE5525	HB8292●	HD1232	
1.3 (HF, HH, HJ, HW eng.)	76-7/85	180	HK9114●	HE5500	HB8702●	HD5002	
			HK2447	HE1240	HB1960	HD1232	
			HK8071●		HB8061●		
1.3 (HK eng.) →eng. 054 060	83→	180	HK2447	HE1240	HB1960	HD1232	
			HK8071●		HB8061●		
1.3 (HK eng.) eng. 054 061→	→7/85	190	HK9186●	HE5525	HB8292●	HD1232	
1.3 (MH eng.)	8/85→						
→eng. 001 000		190	HK9114●	HE5500	HB8702●	HD5002	
eng. 001 001 to 008 561		190	HK9187●	HE5525	HB8292●	HD5002	
eng. 008 562 to 051 000		190	HK9114●	HE5500	HB8702●	HD5002	
eng. 051 001 to 052 706		190	HK9187●	HE5525	HB8292●	HD5002	
eng. 052 707→	→9/90	190	HK9114●	HE5500	HB8702●	HD5002	