









				CLUTCH KIT	COVER ASSEMBLY	DRIVEN PLATE	RELEASE BEARING
			 ins/mm				

## NISSAN-DATSUN - continued

### Prairie

1500 (M10) eng.E15S	82-85	180	HK8203●	HE1220	HB8177●	HD3875
1500 (M10) eng.E15S	2/85-9/88	190	HK8596●	HE5239	HB8372●	HD5340
1800 (M10) eng.CA18S	82-2/85	200	HK8202●	HE1222	HB8184●	HD3875
1800 (M10) eng.CA18S	3/85→	215	HK8597●	HE5316	HB8474●	HD5340
2000 (M10) eng. CA20S	1/86-3/89	225	HK9288●	HE5441	HB9274●	HD5340
2000 4x4 (M11) eng. CA20S	4/89→	215	--	HE5316	--	HD5540

### Silvia

1800 (S10,11) eng.L18E	1/79-9/82	200	HK8197●	HE1222	HB8169●	HD1062
1800 Turbo (S12) eng.CA18T	8/83-7/86	225	HK8603●	HE5272	HB8330●	HD1062
1800 Turbo (S12) CA18T	7/86-3/89	225	HK8604●	HE5272	HB8352●	HD1062
2000 (S12) eng.FJ20E	12/81-7/83	225	HK8606●	HE5273	HB8330●	HD1062
2000 (S12) eng.CA20B	9/83→	225	HK8605●	HE5441	HB8352●	HD1062
2000 (S12) eng.FJ20E	10/83-7/86	225	HK8606●	HE5273	HB8330●	HD1062
2000 (S12) eng.FJ20E	7/86→	225	HK8600●	HE5273	HB8352●	HD1062

### Skyline

2400 (240K) (C110) eng.L24	73-75	225	HK8598●	HE1219	HB8160●	HD1062
2400 (240K) (C210) eng.L24E	79-80	225	HK8606●	HE1219	HB8330●	HD1062

### Stanza

1600, 1800 (T11) eng.CA16, CA18	9/81-86	200	HK8202●	HE1222	HB8184●	HD3875
1700 diesel (T11) eng.CD17T	9/81-86	200	HK8202●	HE1222	HB8184●	HD3875

### Sunny (Inc. Van)

120Y (B210,B310) eng.A12	73-82	180	HK8364●	HE1090	HB8363●	HD1062
140Y, 150Y (B310) eng.A14, A15	78-82	180	HK8366●	HE1220	HB8363●	HD1062
1300 (B11) eng.E13S	82-86	180	HK8365●	HE1090	HB8363●	HD3875
1300 (B12,N13) eng.E13S	10/86→	180	HK8365●	HE1090	HB8363●	HD3875
1400 (N13) eng.GA14S	10/88→	180	HK8367●	HE1220	HB8363●	HD3875
1500 (B11) eng.E15S	82-86	180	HK8367●	HE1220	HB8363●	HD3875
1500 (B12,N13) eng.E15S	86-9/88	190	HK8596●	HE5239	HB8372●	HD5340
1600 (B12,N13) eng.E16S	86→	190	HK8596●	HE5239	HB8372●	HD5340
1600 4WD (B12,N13) eng.E16S	86→	200	HK8202	HE1222	HB8184●	HD3875
1600 (B12,N13) eng.GA16S	89→	190	HK9429●	HE5239	HB9428●	HD5340
1700 diesel (B11) eng.CD17	82-86	180	HK9157●	HE1090	HB8363●	HD5543
1700 diesel (B12,N13) eng.CD17	86→	190	HK9216●	HE5239	HB8512●	HD5340
1800ZX (B12,N13) eng.CA18D	7/89→	215	HK9153●	HE5316	HB8475●	HD5540

### Violet

140J (J710) eng.L14	73-77	180	HK8205●	HE1220	HB8167●	HD1062
140J (A10) eng.A14	77-81	180	HK8366●	HE1220	HB8363●	HD1062
160J (P710,A10) eng.L16S	74-77	200	HK8197●	HE1222	HB8169●	HD1062

### 200SX

1800 Turbo (S13) 16v eng. CA18DT	9/88-8/90	225	HK9300●	HE5649	HB9299●	HD5723
	9/90→	225	HK9500●	HE5649	HB9299●	HD1062