









		RELEASE TYPE		CLUTCH KIT	COVER ASSEMBLY	DRIVEN PLATE	RELEASE BEARING
							
		ins/mm					

ROVER GROUP - continued

3.0 P5 Mk. II, III	65-67	254	HK5709	HA2524	HB1378	HD3261
3.5	67-73	254	HK5709	HA2524	HB1378	HD3261
3500 S	71-77	241	--	HE2860	HB2347	--
3500 ▲ ⁹	76-84	241	HK3738	HE2501 ³	HB3380	HD3264 ³
	84-86	240	HK5596	HE4577	HB3380	HD3822

NOTE: ³Can be replaced by HE4577 and self aligning bearing HD3822 as a set for vehicles 1982→

▲⁹Technical note see page 76.

Range Rover							
3.5 4 speed	70-83	267	HK5206 HK8984●	HE2867	HB3944 HB8054●	HD2430	
3.5 5 speed	83-9/89	267	HK5155 HK8986●	HE2867	HB3953 HB8053●	HD2430	
2.4 Turbo diesel	86→	241	--	--	HB8313●	HD2430	
3.9	9/89-5/91	267	HK9109●	HE5168	HB8311●	HD2430	
3.9 vin No 607103→	6/91→	267	HK9214●	HE5612	HB9213●	HD2430	
Triumph							
Acclaim							
	81-84	190	HK8193●	HE3742	HB8165●	HD1024	
Dolomite							
1300 →WF. 50000	72-75	215	HK5710	HE4787	HB2621	HD3264	
1300 WF. 50001→	75-76	215	HK5039	HE4787	HB3371	HD3264	
1300	76-80	165	HK5038	HE2830	HB2600	HD3268	
1300 (184mm clutch)	79-80	184	HK4978	HE2835	HB2603	HD3268	
1500 & 1500 HL	76-80	184	HK4978	HE2835	HB2603	HD3268	
1850 HL	76-80	215	HK5039	HE4787	HB3371	HD3264	
Dolomite Sprint	73-80	216	HK5711	HE3499	HB2621	HD3264	
GT6							
	66-73	215	HK4842	HE4787	HB1515	HD3264	
Herald							
948 cc.	59-60	159	--	HA2873	HB5084	--	
1200 cc. →GA198953E, also GA198954E→GA201700E intermittent	61-65	159	--	HA3354	HB5084	--	
1200 cc. GA201701E→ plus GA198954E→GA201700E intermittent	66-70	165	HK1015	HE2830	HB1655	HD3268	
12/50→GD76473E	63-65	159	--	HA3354	HB5084	--	
12/50 GA76473E→	65-67	165	HK1015	HE2830	HB1655	HD3268	
13/60	67-71	165	HK1015	HE2830	HB1655	HD3268	
Spitfire							
Mk. I	62-64	159	--	HA3354	HB5084	--	
Mk. II	65-67	165	HK1015	HE2830	HB1655	HD3268	
Mk. III	67-70	165	HK1015	HE2830	HB1655	HD3268	
Mk. IV	71-74	165	HK5035	HE2830	HB1660	HD3268	
1500 ch. FH 75001→	74-80	184	HK4978	HE2835	HB2603	HD3268	
USA only							
→ch. FM28000	70-74	184	--	HE2835	HB1316	HD3268	
ch. FM28001→	74-80	184	HK4978	HE2835	HB2603	HD3268	