









| DRIVEN PLATE | DRIVEN PLATE | COVER ASSEMBLY | CLUTCH KIT | CLUTCH KIT | CLUTCH KIT | COVER ASSEMBLY | DRIVEN PLATE | RELEASE BEARING |
|---|---|---|---|---|---|---|---|-----------------|
|  |  |  |  |  |  |  |  | |

VAUXHALL - continued

Nova

| | | | | | | |
|--|--------|-----|---------|--------|---------|--------|
| 1.0S →eng.3431955 | 10/82→ | 190 | HK8074● | HE3675 | HB8064● | HD3682 |
| 1.2N →eng. 1129939 | | | | | | |
| 1.2S →eng. 1696435 & →eng. 19505999 | | | | | | |
| 1.3N, 1.3S, →eng. 1696057 | | | | | | |
| 1.3i (cat converter) →eng. 1696057 | | | | | | |
| 1.3N, 1.3S →eng. 1956999 | | | | | | |
| 1.3i (cat converter) →eng. 19569999 | | | | | | |

| | | | | | | |
|-------------------------------------|--|-----|---------|--------|---------|--------|
| 1.0S eng. 3431956→ | | 190 | HK9075● | HE5127 | HB8445● | HD5005 |
| 1.2N eng. 1129940→ | | | | | | |
| 1.2S eng. 1696436→ & eng. 19506000→ | | | | | | |
| 1.3N, 1.3S eng. 1696058→ | | | | | | |
| 1.3i (cat converter) eng. 1696058→ | | | | | | |
| 1.3N, 1.3S eng. 1957000→ | | | | | | |
| 1.3i (cat converter) eng. 1957000→ | | | | | | |

| | | | | | | |
|-----------|-------|-----|---------|--------|---------|--------|
| 1.4, 1.4i | 8/90→ | 190 | HK9075● | HE5127 | HB8445● | HD5005 |
|-----------|-------|-----|---------|--------|---------|--------|

| | | | | | | |
|----------|-------|-----|---------|--------|---------|--------|
| 1.6i GTE | 5/88→ | 200 | HK9076● | HE5033 | HB8448● | HD5005 |
|----------|-------|-----|---------|--------|---------|--------|

Ventora

| | | | | | | |
|-----------------------------|-------|-----|--------|--------|--------|--------|
| FD Mk. I & II →ch. OV252009 | 68-70 | 215 | -- | HE5132 | HB1512 | HD3267 |
| heavy duty | | 216 | -- | -- | HB1512 | HD3267 |
| ch. OV252010→ | 70-72 | 241 | HK5631 | HE3769 | HB1363 | HD3267 |
| FE 3300 | 72-76 | 241 | HK5631 | HE3769 | HB1363 | HD3267 |

Victor

| | | | | | | |
|-------------------------|-------|-----|--------|--------|--------|--------|
| FB 1600 cc. ch. 425001→ | 63-65 | 203 | HK1023 | HA2517 | HB1333 | HD3266 |
| FC 1600 cc. | 65-67 | 203 | HK1023 | HA2517 | HB1333 | HD3266 |
| FD 1600 cc. | 67-69 | 190 | HK1022 | HE2837 | HB1603 | HD3267 |
| FD 1600 cc. | 69-72 | 215 | -- | HE4787 | HB2610 | HD3267 |
| FD 2000 cc. | 67-72 | 215 | HK4843 | HE4787 | HB1513 | HD3267 |
| FD 3300 cc. | 68-72 | 215 | -- | HE5132 | HB1512 | HD3267 |
| heavy duty | | 216 | -- | HE2497 | HB1512 | HD3267 |
| FE 1800 cc. | 72-76 | 216 | HK2815 | HE3499 | HB2610 | HD3267 |
| FE 2300 cc. | 72-76 | 216 | HK2817 | HE3499 | HB2614 | HD3267 |
| FE 3300 cc. | 72-76 | 241 | HK5631 | HE3769 | HB1363 | HD3267 |

Viscount, Velox & Cresta

| | | | | | | |
|------------------------------|-------|-----|--------|--------|--------|--------|
| PB/PC 3300 cc. →ch. 1V324999 | 65-70 | 215 | -- | HE5132 | HB1512 | HD3267 |
| heavy duty | | 216 | -- | HE2497 | HB1512 | HD3267 |
| ch. 1V325000→ | 70-72 | 241 | HK5631 | HE3769 | HB1363 | HD3267 |